



Project-information

Project name:
Hillcrest

Contract number:
1138

Contact:
Saitesh Patel

Date:
23/05/2007

Client **Hillcrest Pharmacies Limited**
 Contact: **Mrs Patel**
 Position:
 Road **104-106 Holland Park Avenue**
 Town **London**
 County **W11 4UA**
 Telephone: **020 7727 6350**
 Fax:
 Mobile:
 E-Mail:

Site
 Contact:
 Position:
 Road
 Town
 County
 Telephone:
 Fax:
 Mobile:
 E-Mail:

Contractor **London Drainage Facilities**
 Contact: **Lucie Fuller**
 Position: **Administration**
 Road **PO Box 2728**
 Town **Romford, Essex**
 County **RM4 1XF**
 Telephone: **0870 116 2179**
 Fax: **0870 919 2179**
 Mobile:
 E-Mail: **lucie@london-drainage.com**

No.: 1	PLR: MH 1 X	Date: 23/05/2007	Operator: Danny	Job nr.: 1138	Tape No.: DVD
Cleaned:	Present:	Catchment:	Vehicle: CE56 UUJ	Map No.1:	Map No.2:
Road:	104-106 Holland Park Avenue		start MH: MH 1	Material: Vitrified Clay	
Town:	London, W11 4UA		end MH: Sewer	Size/Shape: Circular, 150	
Location:	Basement Area		section length: 7.5 m	Joint length:	
Reason for inspection:	Follow up survey		Section use: Combined	Year laid:	
Remark: Excavation required to repair					





Inspection report

Date: 23/05/2007	Job N°: 1138	Weather: Dry	Operator: Danny	section number: 1	PLR: MH 1 X
Present:	Vehicle: CE56 UUJ	Camera:	Preset:	Cleaned:	Grade:

Road: 104-106 Holland Park Avenue	Division:	start MH: MH 1
Place: London, W11 4UA	District:	end MH: Sewer
Location: Basement Area	Tape No.: DVD	Total length: 7.5 m

Purpose: Follow up survey	Size/Shape: Circular 150
Use: Combined	Material: Vitrified Clay Pipe length:
Catchment:	Lining: No
	Category:

Comment: **Excavation required to repair**
 Location details: **broken section of pipe, and liner needed aswell**

1:75	position	code	observation	grade	
Depth: 280mm					
	MH 1	0.00	ST Start of Survey	(Misc) 0	
		0.50	S1 CL Longitudinal Crack, at 12 o'clock, Start	(Struct) 2	0.5 m // 00:00:00
		1.20	JDS Joint displaced. Small	(Struct) 1	
		1.82	JDS Joint displaced. Small	1	1.2 m // 00:00:00
		2.30	JDM Joint displaced. Medium	(Struct) 1	
		3.10	JDM Joint displaced. Medium	(Struct) 1	1.2 m // 00:00:00
		3.70	JDM Joint displaced. Medium	(Struct) 1	
		4.30	JDM Joint displaced. Medium	(Struct) 1	3.1 m // 00:00:00
		4.90	JDS Joint displaced. Small	(Struct) 1	
		5.50	OJL Open joint large	(Struct) 2	3.7 m // 00:00:00
		6.20	JDM Joint displaced. Medium	(Struct) 1	
		6.20	PT Pipe tumbles down to Sewer	0	4.3 m // 00:00:00
		6.60	CL Longitudinal Crack, at 02 o'clock	(Struct) 2	
	Sewer	7.10	B Broken Pipe - Base bend on tumbler before main sewer has broken	(Struct) 5	

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection photos

Place: London, W11 4UA	Road: 104-106 Holland Park Avenue	Date: 23/05/2007	section number: 1	PLR: MH 1 X
----------------------------------	---	----------------------------	-----------------------------	-----------------------



Photo: 3a, Tape No.: DVD, 00:00:00
0.5m, Longitudinal Crack, at 12 o'clock, Start



Photo: 4a, Tape No.: DVD, 00:00:00
1.2m, Joint displaced. Small



Photo: 1_6a, Tape No.: DVD, 00:00:00
3.1m, Joint displaced. Medium



Photo: 8a, Tape No.: DVD, 00:00:00
3.7m, Joint displaced. Medium

Inspection photos

Place: London, W11 4UA	Road: 104-106 Holland Park Avenue	Date: 23/05/2007	section number: 1	PLR: MH 1 X
----------------------------------	---	----------------------------	-----------------------------	-----------------------



Photo: 9a, Tape No.: DVD, 00:00:00
 4.3m, Joint displaced. Medium



Photo: 1_10a, Tape No.: DVD, 00:00:00
 5.5m, Open joint large



Photo: 1_13a, Tape No.: DVD, 00:00:00
 6.6m, Longitudinal Crack, at 02 o'clock



Photo: 2a, Tape No.: DVD, 00:00:00
 7.1m, Broken Pipe - Base bend on tumbler before main sewer has broken